

Alert number	<u>A12/00390/21</u>
Notifying country	Germany
Product category	Motor vehicles
Type	Consumer
Product	Passenger car
Name	3
Brand	Bmw
EC-type approval/model	Type-approval number: e1*2007/46*0314*, *0315*, *0316* Types: 3L, 3K, 3C
Production dates	The affected vehicles were manufactured between 20 July 2004 and 8 July 2011.
Company recall code	0061830500, 0061660400, 0061830400
Product description	Passenger car
Risk type	Fire Injuries
Risk description	The vehicles may be affected by frictional corrosion on the connector from the wiring harness to the blower control unit. Over time, this may cause damage to the insulation of the wiring harness, which could trigger a short circuit. This could cause a vehicle fire, even when the engine is switched off.
Legal provisions (at EU level) and European standards against which the product was tested and did not comply	
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer

Products were found and
measures were taken also
in

Bulgaria
Denmark
Estonia
Finland
France
Greece
Croatia
Ireland
Luxembourg
Poland
Portugal
Sweden
Slovenia
Slovakia