

Seat heating cannot be activated on vehicles without SA code 275

Topic number	LI91.30-P-069668
Version	1
Function group	91.30 Seat heater, seat ventilation
Date	04-09-2019
Validity	Vehicles in model series 177 and model series 167 without SA code 275
Reason for change	
Reason for block	

Complaint:

The seat heating in the vehicle cannot be activated. When the seat heating button is pressed the 3 red LEDs light up briefly and then go off again after a brief period (approx. 3 seconds).

Cause:

To prevent too high surface temperatures on the heating surfaces (and thereby any damage to the system), frequent activation of the seat heating is limited.

Consequences:

- Full operation of the seat heating results in the system's heat limit being reached (counter value in background)
- Seat heating can only be started again after a cooling-down phase (counter value must be reset to 0)
- If the vehicle is parked before resetting the value to 0, this may prevent the system from being activated the next time the ignition is operated

Remedy:

The seat heating requires at least the same cooling-down period with the ignition switched-on as the heating was operated for.

Parts with corrected software, which noticeably increases the availability of the seat heating, is expected to be available as from 10/2019.

Symptoms
Body / Seat / Seat heater/comfort heater / Seat heater nonfunctional